



Instruction guide - Fastcheck FC1000

LOOP TESTING

1. To set up the FC1000, plug it into a mains socket. (not protected by RCD)
2. Take a calibrated Loop tester, plug it into the socket on the FC1000 and select PE. Depress the button on the Loop Tester and record local Loop reading.
3. Once local Loop reading has been taken, depress button on the FC1000 and select +0.5Ω.
4. Press Button on the loop tester, the meter should be 0.5 Ω higher than the local loop.
5. To test further Loop testers repeat the procedure, your first test on PE should be the same as the local loop; your second test should be 0.5 Ω higher.

RCD TESTING

1. Plug your RCD Tester into the 13A socket on FC1000.
2. Select the RCD function 15mA/50ms on the FC1000 and 30 x ½ on your RCD tester. Press the test button and your RCD tester should read 50ms
3. Select the RCD function 30mA/50ms on the FC1000 and 30 x 1 on your RCD tester. Press the test button and your RCD tester should read 50ms
4. Select the RCD function 150mA/40ms on the FC1000 and 30 x 5 on your RCD tester. Press the test button and your RCD tester should read 40ms

At any time during testing, the top light comes on, you have either selected the wrong settings on your RCD tester or the tester is injecting too much current out and requires re-calibration.

INSULATION Testing

1. Check the leads and battery condition before connecting the insulation tester to the FC1000.
2. Connect the leads to the insulation side of the FC1000.
3. On the UUT (Unit under test), select a voltage range (eg; 250v) and select 1.9 MΩ on the FC1000. Press the button on the Insulation tester, your insulation tester should read Approx 1.9MΩ, and the voltage indication should light up accordingly e.g. (250v).

To check further ranges, press the Δ arrow and select the other settings (9.9MΩ/99MΩ).

Repeat this for the other voltage ranges on your tester.

